



## Underbridging Wales & Western Route Oxford Case Study

H&A Rail were approached to self-deliver all package of works.

- Completed 600m<sup>2</sup> of de-vegetation across two locations (either side of the bridge).
  - Completed all trial holes.
  - Removed all old handrail and ballast retention.
- Supplied and installed 100 linear meters of key clamp handrail.
- Supplied and installed 100 linear meters of newballast retention.
  - Completed 80m<sup>2</sup> of brickwork repairs.
- Supplied and installed new 2.4m high palisade fence and gate.
  - Installed new access point sign.
- Supplied and installed weed suppressant fabric on the embankment.

E: [info@harail.co.uk](mailto:info@harail.co.uk) | T: 0208 611 2790

**The platform for all your inbound railway projects**